UNITED STATES GOVERNI IT

## 2- Way Memo

Subject: Draft Warning Letter concerning Union Manufacturing Inc.

Paul D. Blais, T-2-1 Env. Prot. Specialist RCRA State Programs Section

FOLD

Thru: Bob Mandel, T-3-2 lum (-(3-87) Chief, Field Inspection

INSTRUCTIONS

Use routing symbols whenever possible.

S ER (Originator of message):
Use brief, informal language.
Conserve space.
Forward original and one copy.

RECEIVER (Replier to message):
Reply below the message, keep one copy, return one copy.

DATE OF MESSAGE

**ROUTING SYMBOL** 

1/13/83

T - 3 - 2

SIGNATURE OF ORIGINATOR

Karen Lee O'Regan

TITLE OF ORIGINATOR

Env. Prot. Specialist

MESSAGE

Upon review of the attached warning letter, I recommend that a Compliance Order be issued to the subject facility for the following reasons:

- Failure of the facility to implement a groundwater monitoring system (Compliance Order should be issued per 1/22/82 MacMillan Memorandum).
- Site is unfenced, unmonitored, and accessible to persons or livestock via an unpaved road. Facility is located in an Industrial Park on an Indian Reservation.
- 3. I observed releases of hazardous waste in several locations.
- 4. Damaged containers holding waste in the hazardous waste storage area were open. REPLY
- 5. Up to 21 potential violations of RCRA were observed; 8 of which are potential class I.

According to the criteria for determining an imminent and substantial endangerment, this facility appears to qualify. This determination was made around 12/30, at which time I verbally relayed it to you.

From: Karen O'Regan, Field Investigator Field Inspections Section, T-3-2 DATE OF REPLY

ROUTING SYMBOL

SIGNATURE OF REPLIER

TITLE OF REPLIER

OPTIONAL FORM 27 (Rev. 7-81) GSA FPMR (41 CFR) 101-11.6 NSN 7540-00-082-2447